

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2020

Submitted Date:

08/03/2020

Document Number:

693700569**FIELD INSPECTION FORM**Loc ID 439302 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439484	PIT	AC			-	O'HARE 1-29-11-57 439484	EI

**General Comment:**



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Water FreshLined: ☐Pit ID: 439484Lat: 40.893350Long: -103.780740Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: 

COGCC inspection to verify pit closure. Pit was backfilled, graded and seeded. Pit ID 439484 status is "CL" and Remediation #13230 has been resolved. Recent storms have caused stormwater to carry sediment down access road into reclaimed pit location smothering new growth. Stormwater controls are required to prevent erosion and inhibition of reclamation.

Corrective Action: 

Restore stormwater controls to prevent erosion of access road and deposition of sediment onto undisturbed rangeland or onto pit reclamation area.

Date: 08/18/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402458543	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215834</a>
693700570	Ohare FW Pit, looking north at sediment deposition	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215829">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215829</a>
693700571	Ohare FW Pit, looking east	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215830">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215830</a>
693700572	Ohare FW Pit, looking north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215831</a>