

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2020

Submitted Date:

08/03/2020

Document Number:

700701249

FIELD INSPECTION FORM

Loc ID: 324267 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271103	WELL	PR	03/13/2013	GW	045-09835	SHDELER 31-11D (531E)	PR
429517	WELL	SI	04/01/2020	GW	045-21609	Shideler Fee 31-8B (K31E)	SI
429519	WELL	SI	04/01/2020	GW	045-21610	Shideler Fee 31-6DD (K31E)	SI
429521	WELL	PR	02/28/2013	GW	045-21612	Shideler 31-5C (K31E)	PR
429523	WELL	PR	02/13/2013	GW	045-21614	Shideler Fee 31-8C (K31E)	PR
429525	WELL	SI	09/01/2019	GW	045-21615	Shideler Fee 31-9B (K31E)	SI
429531	WELL	PR	04/08/2013	GW	045-21617	Shideler Fee 31-5CC (K31E)	PR
429533	WELL	PR	02/16/2013	GW	045-21619	Shideler Fee 31-11A (K31E)	PR
429535	WELL	SI	09/01/2019	GW	045-21621	Shideler Fee 31-9BB (K31E)	SI
429538	WELL	PR	02/28/2013	GW	045-21623	Shideler Fee 31-5BB (K31E)	SI
429549	WELL	SI	12/01/2019	GW	045-21631	Shideler Fee 31-6D (K31E)	SI

General Comment:

COGCC Inspection Report Summary

On Monday 8/3/20 at approximately 0930, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus K31E, at Location # 324267 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Unused equipment/debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	hose next to well heads/ debris in tank containment		
Corrective Action:	remove unused equipment/ debris		Date: 08/17/2020

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 12		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	chemical tanks at well heads		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	271103	Type:	WELL	API Number:	045-09835	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	429517	Type:	WELL	API Number:	045-21609	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	last produced 3/1/2020								
Corrective Action:					Date:				
Facility ID:	429519	Type:	WELL	API Number:	045-21610	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	last produced 3/1/2020								
Corrective Action:					Date:				
Facility ID:	429521	Type:	WELL	API Number:	045-21612	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	429523	Type:	WELL	API Number:	045-21614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	429525	Type:	WELL	API Number:	045-21615	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	last produced 8/1/2019								
Corrective Action:					Date:				
Facility ID:	429531	Type:	WELL	API Number:	045-21617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	429533	Type:	WELL	API Number:	045-21619	Status:	PR	Insp. Status:	PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 429535 Type: WELL API Number: 045-21621 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: last produced 8/1/2019

Corrective Action:

Date: _____

Facility ID: 429538 Type: WELL API Number: 045-21623 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: last produced 3/1/2020

Corrective Action:

Date: _____

Facility ID: 429549 Type: WELL API Number: 045-21631 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: last produced 11/1/2019

Corrective Action:

Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Ditches				
Berms		Culverts				
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402458568	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215866
700701255	Photos for K31E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215859