

KP Kauffman - COGCC Follow-up Inspection Photos
Location: Nessu Consolidation OLF Release
Spill ID # 476987 Date 8/05/2020



View of excavation observed at spill id #476987; to the east.



View of excavation observed at spill Id #476987; to the west.

KP Kauffman - COGCC Follow-up Inspection Photos

Location: Nesssu Consolidation OLF Release

Spill ID # 476987 Date 8/05/2020



Excavation and flowlines exposed; The recently repaired section (2nd repair) of the 3" fiberglass Nesssu Consolidation off location flowline is shown right of the arrow.



View of repair completed to Nesssu Consolidation OLF; Bend/ bow can be seen in the repaired section of flowline; cut ends/ repair stub section do not appear to align.

KP Kauffman - COGCC Follow-up Inspection Photos

Location: Nesssu Consolidation OLF Release

Spill ID # 476987 Date 8/05/2020



View of repair completed to Nesssu Consolidation off location flowline; a bolted clamp has been used as part of the flowline repair where the existing pipe and replacement pipe stub do not appear to properly align.



(3) improperly abandoned flowlines were observed exposed from the south wall of excavation at Spill ID # 476987 (only 2 are shown in this photo); flowline cut ends are not sealed per 1105.e.4.

Note the open cut end of a 3" fiberglass flowline to right of the arrow.