

Inspection Photos
Operator: BP America
API: 067-07155
Date: 8/5/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, snakeweed, rubber rabbitbrush, and crested wheatgrass.



Photo 3. View of erosional channel approximately 3 feet wide and 2 feet deep in the eastern project area.



Photo 4. View of musk thistles within the project area that appear to be herbicide-treated (approx. 150 individuals observed).



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, gambel oak, snakeweed, and yellow rabbitbrush.