

Inspection Photos  
Operator: BP America  
API: 067-07124  
Date: 8/5/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses in a grazed condition, as well as rubber rabbitbrush.





Photo 4. View of erosional headcut at the western edge of the project area, where concentrated flows from the access culvert and a drainage swale converge at the well pad.





Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, gambel oak, snakeweed, and yellow rabbitbrush.