

Inspection Photos
Operator: Hilcorp Energy
API: 067-07799
Date: 8/11/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photos 3/4. View of wattles in the northern and northeastern project area that are full of sediment, displaced, and no longer functioning. Wattles are not adequate BMPs in these areas.



Photo 4. View of reference area comprised of ponderosa pine woodland with gambel oak understory, with a mosaic of open grassland largely comprised of smooth brome and western wheatgrass.