

Inspection Photos

API: 071-07584

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/10/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 1. Facing northeast along the access road. The cut slope along the access road has not established vegetation for long term stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 2. The cut slope along the access road has not established vegetation for long term stabilization. There are signs of erosion along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 3. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 4. The cut slope along the access road has not established vegetation for long term stabilization. There are signs of erosion along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 5. Facing south along the access road. There is an erosion channel along the center of the road ascending down the hillside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 6. The cut slope along the access road has not established vegetation for long term stabilization. There are signs of erosion along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 7. Facing northeast along the access road. This portion of the road is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 8. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 9. Facing northeast at the location. The vegetation has not adequately re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 10. Facing southwest toward the location. There are areas bare of vegetation and additional reseeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 11. View of ground cover shows sparse vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 11. Facing southeast at the bottom portion of the location. There is better vegetation growth in this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 11. Facing southwest at the undisturbed reference area vegetation which consists of Blue grama, Western wheat, Sand dropseed, Mtn. Muhly, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07584 | Date: 8/10/2020

Inspection Photos



Photo 11. The photo on the left taken in 2020 compared to the right photo taken in 2016 shows the regression of vegetation at the location. As stated in the 2016 inspection, “There is a dominance of alfalfa and yellow clover growing at the location which may not withstand drought conditions and may not be persistent over time.”

