

Inspection Photos  
Operator: Hilcorp Energy  
API: 067-07550  
Date: 8/11/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, smooth brome, and sand dropseed.





Photos 3. View of musk thistles (approx. 25) in a flowering/seeding condition within the western project area.





Photo 4. View of reference area comprised of ponderosa pine woodland and gambel oak shrubland, with a mosaic of sagebrush shrubland and open grassland comprised of fringed sage, black sage, smooth brome, and western wheatgrass.