

Inspection Photos
Operator: BP America
API: 067-06800
Date: 8/13/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Surface owner equipment and materials are moved southward, away from the project area.



Photos 3. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing, largely with dense rubber rabbitbrush.



Photo 4. View of the western cut-slope facing northward. Berm is installed and seeded since 2017 reclamation inspection, diversion channel above slope, and cobble run-down. BMPs appear to be functioning. Monitoring needs to continue on slopes where bare soils persist.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, and forbs such as rock goldenrod.