

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/11/2020

Submitted Date:

08/12/2020

Document Number:

700402840

**FIELD INSPECTION FORM**
 Loc ID 415383 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                         | Comment |
|------------------|--------------|-------------------------------|---------|
| Thompson, Bud    |              | BLThomps@BLM.gov              |         |
| Dooling, Jessica | 970-675-4122 | jessica_dooling@xtoenergy.com |         |
| West, Jerry      |              | jerry_west@xtoenergy.com      |         |
| Clark, Erin      | 405-319-3250 | erin_clark@xtoenergy.com      |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 293218      | WELL | PR     | 05/01/2020  | GW         | 103-11106 | YELLOW CREEK<br>FEDERAL 35-12-1 | PR          |

**General Comment:**

A follow up inspection of FIR document 700402159.

The following compliance issues were resolved:

- 1) Missing tank label.

Additional compliance issues:

- 1) Fluid leaking at water tank off loading valve and leaving secondary containment. Photos 5, 6, 7. Complete by 9-11-2020.

This is a summary of inspection report 700402840.

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |
| Type               | LOCATION |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

|                                   |                   |       |                 |
|-----------------------------------|-------------------|-------|-----------------|
| <b>Equipment:</b>                 |                   |       | corrective date |
| Type: Horizontal Heated Separator | # 1               |       |                 |
| Comment:                          |                   |       |                 |
| Corrective Action:                |                   | Date: |                 |
| Type: Other                       | # 1               |       |                 |
| Comment:                          | Pump in building. |       |                 |
| Corrective Action:                |                   | Date: |                 |
| Type: Plunger Lift                | # 1               |       |                 |

|                           |                     |       |  |
|---------------------------|---------------------|-------|--|
| Comment:                  |                     | Date: |  |
| Corrective Action:        |                     | Date: |  |
| Type: Ancillary equipment | # 1                 |       |  |
| Comment:                  | Chemical container. | Date: |  |
| Corrective Action:        |                     | Date: |  |
| Type: Deadman # & Marked  | # 4                 |       |  |
| Comment:                  |                     | Date: |  |
| Corrective Action:        |                     | Date: |  |
| Type: Bird Protectors     | # 1                 |       |  |
| Comment:                  |                     | Date: |  |
| Corrective Action:        |                     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CONDENSATE         | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 5 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|          |  |                     |                     |             |
|----------|--|---------------------|---------------------|-------------|
| Type     | Capacity   | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal    | Adequate   | Walls Insufficient  |                     |             |
| Comment: | Fluid leaking out liner from leak at off loading valve plug. |                     |                     |             |

Inspector Name: Moran, Rick

|                    |   |       |            |
|--------------------|---|-------|------------|
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 09/11/2020 |
|--------------------|---|-------|------------|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 293218         | Type: WELL | API Number: 103-11106 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            |                         |                       | Material Handling And Spill Prevention | Pass                     |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402464894    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221961</a> |
| 700402841    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221949</a> |