

Inspection Photos
Location Name: VPR C NO. 41
API#: 05-071-07276
INSP. #: 695103166



Colorado Oil & Gas Conservation Commission
36.99705, -104.79015, 2423.0m, 144°
2020/08/18 12:58:53

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
36.99702, -104.79018, 2425.0m, 132°
2020/08/18 12:59:04

PHOTO 2: WELL SIGN



Inspection Photos

Location Name: VPR C NO. 41

API#: 05-071-07276

INSP. #: 695103166



PHOTO 3: APPREARS THAT GEAR BOX ON PUMP JACK IS LEAKING OIL. REMOVE AND DISPOSE OF IMPACTED SOIL, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 11-18-20.



PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD. REMOVE IMPACTED SOIL, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 11-18-20.