


## Issue Report

# Pelton Twin #1-SWD, 017-06482, Mull Drilling

Report created on August 14, 2020


Captured: August 7, 2020



Type	Count
Leak	1
Other	1
Weather Damage	1

No.	Summary	Type	Created	Status
3	Earthen berms on east side of battery filled with rain water.	Other	Aug 14, 2020 at 2:59pm	Open
2	Oil contained inside metal berm.	Leak	Aug 14, 2020 at 2:51pm	Open
1	Lightning Strike, Remains of tanks	Weather Damage	Aug 14, 2020 at 2:49pm	Open

## Leak



No.	Summary	Created	Status
2	Oil contained inside metal berm.	Aug 14, 2020 at 2:51 PM	Open



**No. 2 OPEN****Captured: Aug 7, 2020 at 2:53pm****Type**  
Leak**Lat/Long**  
38.87929, -102.33303**Summary**  
Oil contained inside metal berm.**Created**  
Aug 14, 2020 at 2:51pm by Craig Quint



## Other



No.	Summary	Created	Status
3	Earthen berms on east side of battery filled with rain water.	Aug 14, 2020 at 2:59 PM	Open

No. 3 OPEN

Captured: Aug 7, 2020 at 2:53pm



Type  
Other


Lat/Long  
38.87931, -102.33284

Summary  
Earthen berms on east side of battery filled with rain water.

Created  
Aug 14, 2020 at 2:59pm by Craig Quint



## Weather Damage




No.	Summary	Created	Status
1	Lightning Strike, Remains of tanks	Aug 14, 2020 at 2:49 PM	Open



No. 1 OPEN

Captured: Aug 7, 2020 at 2:53pm

**Type**

Weather Damage

**Lat/Long**

38.87936, -102.33310

**Summary**

Lightning Strike, Remains of tanks

**Created**

Aug 14, 2020 at 2:49pm by Craig Quint