

Inspection Photos
Operator: Catamount Operating
API: 067-07917
Date: 8/18/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of area recently disturbed for stormwater diversion. Soils need to be stabilized with mulch and vegetation.



Photo 3. View of stormwater diversion northwest of the project area with boulders in place. Stormwater erosion appears to be controlled at this time.



Photo 4. View of the western fill slope from the northwestern project area facing southward. Revegetation is progressing with grasses such as crested wheatgrass, rubber rabbitbrush, and smooth brome.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, needleandthread grass and forbs such as *Heterotheca villosa* and Townsend daisy.