

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2020

Submitted Date:

08/14/2020

Document Number:

696201643

FIELD INSPECTION FORMLoc ID 316345 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 26155

Name of Operator: EAGLE OPERATING INC

Address: 2501 6TH ST SE STE B

City: MINOT State: ND Zip: 58701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		eagleop@yahoo.com	
		nkbrehkus@gmail.com	
		bakke@rtc.coop	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268007	WELL	DA	10/20/2004	DA	103-10317	E-M EMERALD C-2HZ	RI
316345	LOCATION	CL			-	E-M EMERALD-62N103W 36SENW	RI

General Comment:

On 8/13/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Eagle Operating Inc's E-M Emerald C-2HZ location in Rio Blanco County, Colorado.

This inspection is to document compliance for the following corrective actions from Field Inspection Report No. 696201283:
1002.f: Stormwater Management

It was observed in this inspection that erosion degradation has been repaired.

The following compliance issues were observed during this inspection:
1004.e

Refer to the "Reclamation" and "Stormwater" section of this inspection report for additional details.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	268007	Type:	WELL	API Number:	103-10317	Status:	DA	Insp. Status:	RI
Facility ID:	316345	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____ In _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present **Fail** _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

	<p>Inspection #696201283 observed that Location is predominantly undesirable weedy plant species and stated that ongoing weed management is required until Location receives a passing final reclamation inspection.</p> <p>It was observed in this inspection that ongoing weed management pursuant to Rule 1004.e does not appear to be occurring; Halogeton was observed to have established throughout the Location. This is a Colorado State listed noxious weed.</p>	
Corrective Action:	<p>Comply with Rule 1004.e and conduct weed management. Ongoing weed monitoring/management required until Location receives a passing final reclamation inspection.</p>	Date 08/29/2020
<p>Overall Final Reclamation <input type="checkbox"/> Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/></p>		
Storm Water:		
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs
<p>Comment: Inspection #696201283 observed erosion degradation on the southeastern areas of the Location and required Operator to comply with 1002.f</p> <p>It was observed in this inspection that work to repair erosion has been conducted.</p> <p>Continue compliance with 1002.f; ongoing stormwater monitoring/managment required until Location receives a passing final reclamation inspection.</p>		
Corrective Action:		Date:
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402467159	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5224321
696201644	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5224313