

Inspection Photos

Operator: Hilcorp Operating
API: 067-08319
Date: 8/20/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Little desirable vegetation observed within the interim reclamation areas. Observable vegetation is comprised of kochia weeds up to 5 feet tall, which will dry, break off, and become weed debris.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Little to no desirable vegetation observed here.



Photo 4. View of equipment that is not in service near the wellhead.



Photo 5. View of reference area comprised of irrigated grass field. Comprised of grasses such as smooth brome, foxtail barley, and wheatgrasses.