

Inspection Photos

Location Name: Aggregate State Fluid Recycling Facility Kerr-McGee (#47120)

CE&P Facility ID: 456644; Location ID: 434766

November 20, 2019



CE&P Facility ID: 456644, Entrance off of CR 31.



CE&P Facility ID: 456644 entrance.



Inspection Photos

Location Name: Aggregate State Fluid Recycling Facility Kerr-McGee (#47120)

CE&P Facility ID: 456644; Location ID: 434766

November 20, 2019



Entrance to CE&P Facility.



Open access.



Inspection Photos

Location Name: Aggregate State Fluid Recycling Facility Kerr-McGee (#47120)

CE&P Facility ID: 456644; Location ID: 434766

November 20, 2019



Gate lying on the ground.



Open gate and southern perimeter fence.



Inspection Photos

Location Name: Aggregate State Fluid Recycling Facility Kerr-McGee (#47120)

CE&P Facility ID: 456644; Location ID: 434766

November 20, 2019



View of CE&P Facility from southern boundary looking north.



Entrance from CR 31.