

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

08/25/2020

Document Number:

690900118**FIELD INSPECTION FORM**Loc ID 434766 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Taylor		taylor_Rowley@oxy.com	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456644	CENTRALIZED EP WASTE MGMT FAC	AC	08/17/2018		-	Aggregate State Fluid Recycling 37C-16HZ	EI

General Comment:

On November 20, 2019, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of KERR MCGEE OIL & GAS ONSHORE LP; Location ID: 434766, CE&P ID: 456644. Taylor Rowley with Kerr McGee was on Location. Weather was overcast and temperature low from the low 40s down to the high 30s. It was requested that all cell phones and cameras be left in the vehicles. All photos are from a distance.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	<p>A portion of the souther perimeter fence had a breach and an open gate entry which is not controlling public access.</p> <p>Per Rule 908.b.(5)C., the facility shall be designed to control public access, prevent unauthorized vehicular traffic, provide for site security both during and after operating hours, and prevent illegal dumping of wastes. Appropriate measures shall also be implemented to prevent access to the centralized facility by wildlife or domestic animals.</p>		
Corrective Action:	Comply with Rule 908.b.(5)C	Date:	09/09/2020

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 456644 Type: CENTRALIZE API Number: - Status: AC Insp. Status: EI

COGCC Comments

Comment	User	Date
<ul style="list-style-type: none"> • The facility receives both liquid and solid waste from Kerr-McGee's exploration and production waste streams for treatment. • Gate along southern fence open and on the ground. • Storm water detention pond located in the northwest corner of the facility. • Mixing bins along the central western portion of the facility. • Vertical cutting dryer (VCD) dries cutting to 2% oil along the central eastern portion of the facility. 	fischera	08/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900119	CE and P Facility ID 456644 20191120 Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231426