

Inspection Photos
Operator: BP America
API: 067-09199
Date: 8/25/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass and intermediate wheatgrass. Approximately 300 musk thistles appear to be herbicide-treated within the project area.



Photo 3. View of stockpiled materials stored within the northwestern corner of the well pad.



Photo 4. View of reference area comprised of irrigated field, with irrigated grasses, rushes, and sedges.