

Inspection Photos  
Operator: BP America  
API: 067-07203  
Date: 8/25/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the southern fill slope facing westward. Revegetation is progressing with western wheatgrass and smooth brome.





Photo 3. View of the western project area from the southwestern corner facing northward. Stormwater BMPs are installed.



Photo 4. View of wattle on the northwestern cut-slope that is filled with sediment. Wattle does not appear to be an adequate BMP to stabilize this area.





Photo 5. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, Sandberg bluegrass, and forbs such as purple aster.