

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2020

Submitted Date:

08/27/2020

Document Number:

700403118**FIELD INSPECTION FORM**

Loc ID 314354 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10605Name of Operator: APEX OIL VENTURES INCAddress: 8823 S. REDWOOD ROAD #D-1City: WEST JORDAN State: UT Zip: 84088**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Callister, Jan	801-487-4721	jec-apex@outlook.com	
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228525	WELL	PR	04/01/2020	GW	103-05400	P.R.-TRIGOOD-GOV'T (0365) 10	PR

General Comment:

A routine inspection identified the following compliance issues:

1) Remove old operator sign located at pump jack. Photo 5. Complete by 9-27-2020.

This is a summary of inspection report 700403118.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Remove old operator well sign located at pump jack.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/27/2020

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pump jack power disconnected.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	228525	Type:	WELL	API Number:	103-05400	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Tubing valve close. Casing valve open at well head. Casing gage 90 psi.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700403119	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233327