

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/27/2020

Document Number:

697001934**FIELD INSPECTION FORM**Loc ID 420414 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420412	WELL	TA	08/01/2019	GW	123-32569	FIVE RIVERS K 03-33D	PA
420413	WELL	TA	02/10/2018	GW	123-32570	FIVE RIVERS USX K 09-01D	PA
420418	WELL	TA	03/01/2019	GW	123-32574	FIVE RIVERS K 10-30D	PA
420422	WELL	TA	09/01/2019	GW	123-32578	FIVE RIVERS USX K 09-17D	PA

**General Comment:**

All wells associated with the tank battery have been P&amp;A, all production equipment remains intact on location.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	x 4		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused ECD's, meter run, separators, separator dump and ECD lines, ECD scrubbers, crude oil tanks and produced water vaults.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/30/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other	# 2		
Comment:	ECD scrubbers		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Multiple tube meter run		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	<100 BBLs	PBV CONCRETE		,	
Comment:		60 bbls				
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: <u>420412</u>	Type: <u>WELL</u>	API Number: <u>123-32569</u>	Status: <u>TA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>420413</u>	Type: <u>WELL</u>	API Number: <u>123-32570</u>	Status: <u>TA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>420418</u>	Type: <u>WELL</u>	API Number: <u>123-32574</u>	Status: <u>TA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>420422</u>	Type: <u>WELL</u>	API Number: <u>123-32578</u>	Status: <u>TA</u>	Insp. Status: <u>PA</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Thursday 8/27/2020 at approximately 10:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Five Rivers K10-30D Pad location #420414 in Weld County, Colorado.</p> <p>While there, I observed that all wells on the pad have been plugged and abandoned. The well pad and lease roads from the pad to the county road and to the tank battery have been reclaimed and re-seeded. All production remains intact on the production pad. During this inspection the following possible compliance issues were observed: Rule 603.f. with a corrective action date of 11/30/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	08/27/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
697001935	Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233714">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233714</a>