

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/27/2020

Document Number:

699302442**FIELD INSPECTION FORM**Loc ID 319478 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427549	WELL	SI	04/01/2020	GW	123-35027	SADDLEBACK 21-29	SI
427554	WELL	SI	04/01/2020	GW	123-35029	SADDLEBACK 31-29	SI
427556	WELL	SI	04/01/2020	GW	123-35030	SADDLEBACK 30-29	SI
427557	WELL	SI	04/01/2020	OW	123-35031	SADDLEBACK 6-29X	SI
427558	WELL	SI	04/01/2020	GW	123-35032	SADDLEBACK 4-29	SI
427572	WELL	SI	04/01/2020	OW	123-35035	SADDLEBACK 29-29	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate x 6		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	privacy chainlink topped with barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	privacy chainlink topped with barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	privacy chainlink topped with barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	privacy chainlink topped with barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	card in meter house indicates current callibration		
Corrective Action:		Date:	
Type: Ancillary equipment	# 12		

Comment: automation		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 6	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 3	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 6	
Comment: partially exposed at surface		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: Shares containment with crude tanks, Sink hole formed under PW tank causing tank to sink down on North side.				
Corrective Action: Comply with Rule 906.d.(1)				Date: 11/27/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity) 315 bbl

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		

Inspected Facilities

Facility ID: 427549 Type: WELL API Number: 123-35027 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300518 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 427554 Type: WELL API Number: 123-35029 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300552 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 427556 Type: WELL API Number: 123-35030 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300487 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 427557 Type: WELL API Number: 123-35031 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300498 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 427558 Type: WELL API Number: 123-35032 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300464 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 427572 Type: WELL API Number: 123-35035 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 4/1/2020, Form 42(PR) Doc # 402300541 submitted 1/31/2020 and is approved.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 8/27/2020 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Saddleback 6-29 at Location</p> <p>#319478 in Weld County Colorado.</p> <p>While there, I observed a Multi-well pad & tank battery. Saddleback 21-29: SI since 4/1/2020, Form 42(PR) Doc # 402300541 submitted 1/31/2020 and is approved. Saddleback 31-29: SI since 4/1/2020, Form 42(PR) Doc # 402300552 submitted 1/31/2020 and is approved. Saddleback 30-29: SI since 4/1/2020, Form 42(PR) Doc # 402300487 submitted 1/31/2020 and is approved. Saddleback 6-29x: SI since 4/1/2020, Form 42(PR) Doc # 402300498 submitted 1/31/2020 and is approved. Saddleback 4-29: SI since 4/1/2020, Form 42(PR) Doc # 402300464 submitted 1/31/2020 and is approved. Saddleback 29-29: SI since 4/1/2020, Form 42(PR) Doc # 402300541 submitted 1/31/2020 and is approved.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>906.d.(1) berms/secondary containment: Sinkhole has formed under PW tank causing it to sink on the North side. CA date 11-27-2020, see photos 21-24.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	08/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302443	location pisc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233974