

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/27/2020

Document Number:

700701428**FIELD INSPECTION FORM**
 Loc ID 420223 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420217	WELL	PR	08/29/2012	GW	045-20107	McLin C7	PR
420236	WELL	PR	08/29/2012	GW	045-20112	McLin C2	PR
420279	WELL	PR	03/03/2014	GW	045-20113	McLin C3	PR
420289	WELL	PR	03/30/2012	GW	045-20117	McLin C16	PR
420291	WELL	PR	03/03/2014	GW	045-20118	McLin C5	PR
420329	WELL	PR	10/29/2012	GW	045-20130	McLin C20	PR
420331	WELL	PR	08/29/2012	GW	045-20131	McLin C13	PR
420332	WELL	PR	11/30/2013	GW	045-20132	McLin C15	PR
420333	WELL	PR	08/29/2012	GW	045-20133	McLin C24	PR
420336	WELL	DG	10/08/2019	LO	045-20135	McLin C8	DG
420338	WELL	DG	10/08/2019	LO	045-20136	McLin C17	DG
420340	WELL	PR	08/29/2012	GW	045-20138	McLin C23	PR
420341	WELL	PR	10/29/2012	GW	045-20139	McLin C19	PR
420343	WELL	PR	10/29/2012	GW	045-20140	McLin C18	PR
420344	WELL	PR	08/29/2012	GW	045-20141	McLin C22	PR
420345	WELL	PR	11/30/2013	GW	045-20142	MCLIN C6	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 8/27/20 at approximately 0930, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa McClin C, at Location # 420223 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. All C/A(s) from previous inspection document # 700701297 have been completed.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 14		corrective date
Comment:	All meters calibrated on location within a year.		

Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	one tank is heated					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLS	STEEL AST		,	
Comment:	shared containment with condensate tanks					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420217	Type:	WELL	API Number:	045-20107	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420236	Type:	WELL	API Number:	045-20112	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420279	Type:	WELL	API Number:	045-20113	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420289	Type:	WELL	API Number:	045-20117	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420291	Type:	WELL	API Number:	045-20118	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420329	Type:	WELL	API Number:	045-20130	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420331	Type:	WELL	API Number:	045-20131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420332	Type:	WELL	API Number:	045-20132	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

Facility ID: 420333	Type: WELL	API Number: 045-20133	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 420336	Type: WELL	API Number: 045-20135	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 420338	Type: WELL	API Number: 045-20136	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 420340	Type: WELL	API Number: 045-20138	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 420341	Type: WELL	API Number: 045-20139	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 420343	Type: WELL	API Number: 045-20140	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 420344	Type: WELL	API Number: 045-20141	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 420345	Type: WELL	API Number: 045-20142	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel		Ditches				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701433	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234130">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234130</a>