

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2020

Submitted Date:

08/28/2020

Document Number:

696302344**FIELD INSPECTION FORM**Loc ID 317537 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
REYNOLDS, RODNEY	(316) 337-8340	reynoldsr@berexco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239252	WELL	TA	03/01/1976	SI	123-07039	MOYER UNIT 14-32	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	STORAGE OF SUPL	
Comment:	Unmarked Risers in the Southwest Corner of Location, see photos	
Corrective Action:	Comply with Rule 603.f.	Date: 09/04/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 239252 Type: WELL API Number: 123-07039 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Last MIT 06.13.2019. Form 21 #402068288 still "In Process"

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 08/26/2020 at approximately 10:30, I, Inspector Erica Petrie, conducted a Field Inspection at Beren Corp, Moyer 14-32 Location #317537 in Weld County, Colorado. While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Unmarked Risers in Southwest corner of Location. Refer to Rule 603.f about unmarked Risers. See Photos. Comply with Rule 603.f. Corrective Action date 09.04.2020</p> <p>MIT was performed on 06.13.2019, Form 21 #402068288 still "IN PROCESS" for approval.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	08/28/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302345	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234853