

Inspection Photos  
Operator: Hilcorp Energy  
API: 067-09816  
Date: 8/27/2020



Photo 1. View of the project area from the northwestern edge facing center.



Photo 2. View of the southern fill slope. Berms are installed. Erosion channels are graded and appear to be seeded.



Photo 3. View of the western project area facing northward. Dense Russian thistle debris needs to be removed.



Photo 4. View of area where re-seeding appears to be conducted. Little desirable vegetation observed. It does not appear that the area was mulched, which likely contributed to poor germination.



Photo 5. View of reference area vegetation comprised of black sagebrush shrubland with grasses and forbs such as Indian ricegrass, lanceleaf buckwheat, and needleandthread grass.