

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402478324

Date Received:

08/31/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>	<u>970 675 3814</u>	<u>SPWU@chevron.com</u>
<u>Sanford, Anita</u>	<u>970-675-3842 970-250-8558</u>	<u>atlx@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402442

Inspection Date: 08/05/2020

FIR Submit Date: 08/19/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 314781

Location Name: WILSON CREEK UNIT-63N94W Number: 26SWSW County: \_\_\_\_\_

Qtrqtr: SWS Sec: 26 Twp: 3N Range: 94W Meridian: 6  
W

Latitude: 40.195623 Longitude: -107.912653

FACILITY - API Number: 05-103-00 Facility ID: 314781

Facility Name: WILSON CREEK UNIT-63N94W Number: 26SWSW

Qtrqtr: SWS Sec: 26 Twp: 3N Range: 94W Meridian: 6  
W

Latitude: 40.195623 Longitude: -107.912653

CORRECTIVE ACTIONS:

1 CA# 141335

Corrective Action: Comply with Rule 603.f. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Properly treat or dispose of oily waste in accordance with 907.e

Date: 09/03/2020

Response: CA COMPLETED

Date of Completion: 08/28/2020

Operator Comment: All tubing connection fitting checked and tightened as needed. Stain removed and discarded. No leaking from tubing at well head has been noted.

COGCC Decision:

COGCC Representative:

2 CA# 141336

Corrective Action: Cover, cap, fill or remove if no longer in use/ necessary.

Date: 09/03/2020

Response: CA COMPLETED

Date of Completion: 08/28/2020

Operator Comment: These were old rig anchors that are OOS. Dug down about 2 feet, cut off anchor pipe and back filled. Anchor is removed.

COGCC Decision:

COGCC Representative:

3 CA# 141337

Corrective Action: Install netting/screen to prevent access by wildlife.

Date: 09/03/2020

Response: CA COMPLETED

Date of Completion: 08/28/2020

Operator Comment: Containment covered with bird netting.

COGCC Decision:

COGCC Representative:

4 CA# 141338

Corrective Action: Install proper guy line markers per Rule 1003.

Date: 09/03/2020

Response: CA COMPLETED

Date of Completion: 08/28/2020

Operator Comment: New anchor marked installed.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: SEE ATT. PHOTOS

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed:

Title: HSE Specialist

Date: 8/31/2020 11:27:39 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402478341	Photo
402478344	Photo
402478345	Photo
402478346	Photo
402478347	Photo
402478348	Photo
402478350	Photo

Total Attach: 7 Files