

Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 418697

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 1: Photo taken from the southeast corner of the Location, facing west. Photo provides an overview of the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 2: Photo taken from the southeast corner of the Location, facing north. Photo provides an overview of the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 3: Photo taken from the southwest corner of the Location. Photo shows perimeter stormwater ditch. Ditch BMP has not been constructed in accordance with good engineering practices; BMP ends on the southwest end of the location and does not have a sufficient outlet to allow for sediment laden-free stormwater discharge.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 4: Photo taken from the from the southwest end of the Location, below ditch in photo 3. Photo shows Operator appears to have repaired the erosion degradation documented in the 5/26/2020 inspection. However, BMPs remain insufficient or missing to protect the slopes, and to allow for sediment laden-free stormwater discharge from the ditch

Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 418697



Photo 5: Photo taken from the southwest corner of the Location, facing northwest. Photo show slopes of Location.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 6: Photo taken from the Ditch BMP on the west end of the Location. Photo shows Operator appears to have installed a velocity check as an outlet; This does not appear to be a sufficient or appropriate long term outlet to allow for sediment laden-free stormwater discharge.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 7: Photo taken from the northwest end of the Location, facing south. Photos shows ditch BMP. BMPs appears insufficient, as stormwater degradation due to runoff is evident below BMPs evident

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 7.b: Continued from photo 7, facing west. Photo shows stormwater erosion has continued and appears to have removed the soils and finer particulates on areas of the Location and the ditch.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 8: Photo taken from the ditch on the northwest end of the Location, facing east. Photo shows stormwater erosion has continued and appears to have removed the soils and finer particulates on areas of the Location and the ditch.

Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 418697



Photo 9: Photo taken from the northwest end of the Location, facing north. Photo shows where topsoil was stored. Photo shows BMPs remain missing, or insufficient to protect slopes, and erosion degradation has continued resulting in loss of soils.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 10: Photo taken from the northwest corner of the Location, facing east. Photo shows perimeter stormwater ditch.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 11: Photo taken from the northwest corner of the Location, facing south. Photo shows perimeter stormwater ditch. .

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 12: Photo taken from the northwest corner of the pad, facing south. Photo shows stormwater ditch is filling with sediment.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 13: Photo taken from the cut slopes on the north end of the Location. Photo shows Operator has failed to implement BMPs to protect and stabilize slopes; erosion degradation has continued. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 14: See comments under photo 13. 6 foot measuring stick for reference. .

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 15: See comments under photo 13. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 418697



Photo 16: Photo taken from the cut slopes on the northeast corner of the Location. Photo shows BMPs remain missing or insufficient to stabilize and protect slopes. 6 foot measuring stick for reference.