

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2020

Submitted Date:

09/01/2020

Document Number:

696201675**FIELD INSPECTION FORM**
 Loc ID 324491 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, '	970-385-0696	inspection@sginterests.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324491	LOCATION	AC			-	Federal 11-90-15 1	RI
436817	WELL	PR	10/28/2017	GW	051-06129	Federal 11-90-15 3	PR

**General Comment:**

On 8/31/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at SG Interests' Federal 11-90-15 1 location in Gunnison County, Colorado.

This inspection is a followup to inspection #696201325, to document compliance with the following corrective actions:

1002.f: Chemicals within containment

1200: Protection of Wildlife Resources

Refer to the "Related Facilities" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Inspected Facilities**Facility ID: 324491 Type: LOCATION API Number: - Status: AC Insp. Status: RIFacility ID: 436817 Type: WELL API Number: 051-06129 Status: PR Insp. Status: PR**Producing Well**

Comment: Inspection #696201325 observed that no BMPs have been implemented to prevent wildlife access at well head cellar.

It was observed in this inspection that BMPs to prevent wildlife access have not been installed at the well head cellar.

Original corrective action and date

Corrective Action: Install BMPs to prevent wildlife access to cellar.

Date: 06/13/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Inspection #696201325 observed that the cellar at well #051-06129 has filled with fluid/chemicals, and required Operator to remove chemicals from within containment.

It was observed in this inspection that chemicals have been removed per the corrective action.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT
**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696201676	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237075</a>