

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2020

Submitted Date:

09/01/2020

Document Number:

690102061**FIELD INSPECTION FORM**Loc ID 330481 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251371	WELL	PR	04/01/2018	GW	123-19174	WESTERN 13-35	EG

General Comment:

Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected FacilitiesFacility ID: 251371 Type: WELL API Number: 123-19174 Status: PR Insp. Status: EG**Flowline**

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Western 13-35) is Temporarily Abandoned; off location flowline disconnected from wellhead. OOSLAT observed on flowline valves at wellhead. COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc #402454141 was received on 08/20/2020; updated to 9/1/2020. The facility services multiple wells; flowlines OOSLAT at facility; horizontal separators and equipment. Noble Energy personnel and contractors were starting work at the facility/ tank battery at the time of this field inspection. NO CA's identified during this field inspection.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102062	Well (TA), Signage and OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237068
690102063	OLF Marked (Pinflagged)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237069
690102064	Facility/ Tank Battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237070