

Inspection Photos
Operator: Hilcorp Energy
API: 067-08082
Date: 8/27/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area reclamation is not conducted here.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Area is not used for production and needs reclamation.



Photo 4. View of the southern edge of the project area facing eastward.



Photo 5. View of reference area vegetation comprised of irrigated grass field with grasses such as orchard grass as well as sedges and rushes such as Baltic rush.