

Inspection Photos
Operator: BP America
API: 067-07161
Date: 9/2/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with smooth brome and ponderosa pine trees.



Photo 3. View of the eastern project area facing northward. Stormwater controls including cobble run-down, are installed.



Photo 4. View of reference area vegetation comprised of ponderosa pine forest with an understory of gambel oaks, Oregon grape, Junegrass, Sandberg bluegrass.