

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2020

Submitted Date:

09/03/2020

Document Number:

693902215**FIELD INSPECTION FORM**Loc ID 325914 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre | | sabre.beebe@bpx.com | All Inspections |
| , | | SanJuanCOGCC@bp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215556 | WELL | SI | 11/01/2019 | GW | 067-07161 | TYCKSEN A 1 | RI |

General Comment:

On 9/1/2020 Catherine Roy conducted a reclamation and stormwater inspection. No compliance issues were documented during this inspection.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | |
|--|---|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
| Final Land Use: _____ | |
| Reminder: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |
| Access Roads _____ | Regraded _____ Contoured _____ Culverts removed _____ |
| Gravel removed _____ | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____ | Dust and erosion control _____ |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
| Weeds present _____ | Subsidence _____ |
| 1004.d. FINAL VEGETATION TRANSECT | |
| TRANSECT RESULTS OF DISTURBED AREA% _____ | |
| TRANSECT RESULTS OF REFERENCE AREA% _____ | |
| TOTAL % OF DESIRABLE VEGETATION COVER _____ | |
| VEGETATIVE COVER _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Stormwater controls are installed and maintained in good working condition at this time.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 693902217 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238874 |