

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #1838 from entrance to location



Photo #1184 from inspection #699801096 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #1839 flow line risers not LO/TO.