

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/02/2020

Submitted Date:

09/02/2020

Document Number:

699801725

FIELD INSPECTION FORMLoc ID 312424 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, BLM		jbyers@blm.gov	
Jordan, Reid		maralextechjr@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221569	WELL	SI	01/01/1999	GW	077-08171	FEDERAL 29-2	TA

General Comment:**COGCC Inspection Report Summary**

On Wednesday 9/2/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW, Location #312424 in Mesa County Colorado.
Refer to document #699801090 inspection conducted on 5/13/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Flow line riser not LO/TO. See photo #1170 and #1828 with a previous corrective action date of 8/13/20. Unused meter run. See photo #1166 and #1827 with a previous corrective action date of 8/13/20. Multiple unmarked deadman. See photo #1168, #1169 and #1830 with a previous corrective action date of 5/27/20. MIT required on well. With a previous corrective action date of 8/13/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Unused meter run. See photo #1166 and #1827			
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location.		Date:	08/13/2020
Type	UNUSED EQUIPMENT			
Comment:	Flow line riser not LO/TO. See photo #1170 and #1828			
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly LO/TO or plug flow line riser.		Date:	08/13/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Pipe rail fence			
Corrective Action:			Date:	
Equipment:				
Type: Deadman # & Marked	# 2			corrective date
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 2			
Comment:	Multiple unmarked deadman. See photo #1168, #1169 and #1830			
Corrective Action:	All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height. Properly mark deadman.		Date:	05/27/2020
Type: Plunger Lift	# 1			

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221569	Type:	WELL	API Number:	077-08171	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Last produced prior to 1999. No MIT on record.									
Corrective Action: All temporarily abandoned wells shall pass a mechanical integrity test. Preform MIT on well.									
Date: 08/13/2020									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801726	Photos for Insp. #699801725	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238912