

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/28/2020

Document Number:

700403126**FIELD INSPECTION FORM**Loc ID 316465 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277796	WELL	PR	03/11/2015	GW	103-10577	HELLS HOLE 6-14	PR

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Gas venting to atmosphere through partially open casing valve. Photo 2. Complete by 9-4-2020.
- 2) Unused tubing & rods lying next to pump jack. Photo 4. Complete by 9-28-2020.
- 3) Tank capacity label volume illegible. Photo 7. Complete by 9-28-2020.
- 4) Missing deadman marker in SW corner of location. Photo 8. Complete by 9-28-2020.
- 5) Location sign at entrance lying on ground. Photo 9. Complete by 9-28-2020.

This is a summary of inspection report 700403126.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label capacity is illegible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/28/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Location sign at entrance lying on ground.		
Corrective Action:	Attach back on posts. Install sign to comply with Rule 210.b.	Date:	09/28/2020

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused tubing & rods lying on ground next to pump jack.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/28/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Gas venting to atmosphere through partially open casing valve.		
Corrective Action:	Close valve.  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/04/2020
Type: Ancillary equipment	# 1		

Comment: <a href="#">Chemical container.</a>		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment: <a href="#">Deadman is missing marker in SW corner of location.</a>		
Corrective Action: <a href="#">Install proper guy line markers per Rule 1003.a</a>		Date: <a href="#">09/28/2020</a>
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 277796	Type: WELL	API Number: 103-10577	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402477433	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234370</a>
700403127	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234366">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234366</a>