

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/28/2020

Document Number:

700600139**FIELD INSPECTION FORM**Loc ID 424805 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, Salene		salenej@gmail.com	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424804	WELL	AL	05/25/2016	LO	043-06205	COHO 24-21	EI
424812	WELL	PR	08/08/2013	LO	043-06207	AURORA 24-21	EI

General Comment:

Pit has been closed but remains open in COGCC database. Operator has not submitted the required Form 27 to close pit. Condition of Approval on Form 27 for Remediation 15381 required operator to submit Form 27 documenting pit closure within 10 days of closure.

Operator shall comply with COGCC COAs and requests on Form 27 402350104 which approved pit closure.

Inspected Facilities									
Facility ID:	424804	Type:	WELL	API Number:	043-06205	Status:	AL	Insp. Status:	EI
Facility ID:	424812	Type:	WELL	API Number:	043-06207	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action:

Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402477819	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234887
700600140	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234886