

Inspection Photos
Operator: BP America
API: 067-08150
Date: 9/1/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northeastern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass and sand dropseed.



Photo 3. View of sediment plume from the well pad cut-slope settled in the northeastern project area.



Photo 3. View of well pad cut-slope showing wattles needing maintenance. Area appears to be hydroseeded.



Sediment flows from
the well pad along the
access road and into
roadside ditch

5.



6.

Photos 5/6. View of sediment flow downstream from the well pad, along the access road (5), and into roadside ditch (6).



Photo 7. View of reference area vegetation comprised of mixed gambel oak and ponderosa pine woodland, with pinyon and juniper trees, shrubs such as mountain mahogany and antelope bitterbrush, as well as grasses and forbs such as Indian ricegrass, James galleta, and bricklebrush.