

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2020

Submitted Date:

09/04/2020

Document Number:

688800785

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|--------------------------|---------------------------------------|
| Heil, John | | john.heil@state.co.us | |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Beebe, Sabre | | sabre.beebe@bpx.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|---------------|-------------|
| 215596 | WELL | PR | 06/01/2020 | GW | 067-07201 | STATE CB 1 | EI |
| 477136 | SPILL OR RELEASE | AC | | | - | State CB 1 | EI |

General Comment:

On August 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP State CB #1. For the most recent field inspection report of this facility, please refer to document #688800750. The purpose of this site visit was to inspect Spill/Release Point ID #477662.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|--|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Free standing sign near location entrance. New operator label has been placed over previous operator's name. | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | New operator contact information on metal secondary containment ring. | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--------------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Posted on location sign. | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|--|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel enclosure. | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Stock panel enclosures around all equipment on site. | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | Steel pipe barricade fencing around valve can. | | |
| Corrective Action: | | | Date: |
| Type | LOCATION | | |
| Comment: | Perimeter fencing. | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------------|---|--|-------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 6 | | |
| Comment: | Six anchors observed, only 4 were marked. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment. | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Valve can with barricade fencing. | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | 37.101753,-107.546775 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95 bbl. | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 215596 Type: WELL API Number: 067-07201 Status: PR Insp. Status: EI

Facility ID: 477136 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: [Please refer to document #402467732 for more information regarding this release.](#)

Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)

Date: 10/05/2020

Reportable: YES

GPS: Lat 37.101766

Long -107.546787

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>On August 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP State CB #1. For the most recent field inspection report of this facility, please refer to document #688800750. The purpose of this site visit was to inspect Spill/Release Point ID #477662.</p> <p>During this inspection, stained soil and gravel were observed from a point source near the PBV. The flow path leaves the location and crosses an agricultural field.</p> | hughesjo | 09/04/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800786 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239576 |