

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2020

Submitted Date:

09/01/2020

Document Number:

696201669

FIELD INSPECTION FORM

Loc ID: 418697 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	970-385-0696	inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418693	WELL	PA	07/11/2019	GW	051-06098	VOLK 12-89-21 #1	RI
418697	LOCATION	CL			-	VOLK 12-89-21 #1	RI

General Comment:

On 8/31/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at SG Interests' Volk 12-89-21 #1 location in Gunnison County, Colorado.

This inspection is a followup to inspection #696201320, to document compliance with the following corrective actions:
1002.f.(2)C: Install or repair required BMPs in accordance with good engineering practices by 6/11/2020.

It was observed in this inspection that the Location remains out of compliance with 1002.f.(2)C

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 418693 Type: WELL API Number: 051-06098 Status: PA Insp. Status: RI

Facility ID: 418697 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					
Other	Fail					BMPs on cut/fill slopes

Comment: Inspection #696201320 observed that stormwater and erosion control BMPs on the Location were insufficient, or missing pursuant to 1002.f.(2)C. Operator was required to comply with 1002.f.(2)C by 6/11/2020.

It was observed in this inspection that Location remains out of compliance with 1002.f stormwater rules. BMPs remain missing or insufficient to protect and stabilize the cut and fill slopes of the Location; Erosion degradation evident. Stormwater ditch BMPs on the perimeter of the pad, and the western areas of the Location have not been constructed in accordance with good engineering practices, including a sufficient outlet to allow for sediment laden-free stormwater discharge.

Original CA has not been addressed and remains applica ble.

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C. Conduct revegetation/reseeding activities on the slopes and install erosion controls to stabilize the seeded soil.

Date: 06/11/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402480028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237079
696201670	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237072