

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484
Remediation Project No. 12158



Photo 1 – Groundwater in northeast portion of the eastern excavation. Sheen observed on the water.



Photo 2 – South and west sidewall of eastern excavation. Flowlines exposed in portions of the excavation.

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484
Remediation Project No. 12158



Photo 3 – Flowlines exposed in eastern excavation



Photo 4 – Fencing in place surrounding western excavation.

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484
Remediation Project No. 12158



Photo 5 – Western excavation has been partially backfilled.