

API: 05-007-06136



Chavez #2 pump jack and well head.



Stained soil around well head.

Inspection Photos
Location Name: Chavez #2
API: 05-007-06136



Impacted material allegedly from the Albert Martinez #1 tank battery.



Stock piled oily soil from the Albert Martinez #1 tank battery.

Inspection Photos
Location Name: Chavez #2
API: 05-007-06136



Impacted material stock piled near Chavez #2.



AST for Chavez #1 and #2 on Chavez #1 location.