

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 pump jack and location sign.



Weeds present near well head and pump jack.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Well head is wet and stained.



Weeds present on location.



Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Domestic gas tap.



Stained soil beneath load out valve on eastern AST.