

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2020

Submitted Date:

09/10/2020

Document Number:

688800798

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320912 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 900 _____
Name of Operator: ALAMOSA DRILLING INC _____
Address: 8150 N. CENTRAL EXPY - STE 750 _____
City: _____ DALLAS _____ State: _____ TX _____ Zip: _____ 75205- _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 _____ Number of Comments
2 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296015	WELL	PR	09/01/2018	OW	007-06253	ALBERT MARTINEZ 1	EI
477321	Domestic Tap	AC	07/23/2020		-	Domestic Tap 18NENE	EI

General Comment:

On September 2, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Albert Martinez #1. For the most recent field inspection report of this facility, please refer to document #688800544.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with contents, capacity, and have NFPA placards.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Tank battery has sign listing contributing well.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near pump jack.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds present near well head and at tank battery.		
Corrective Action:	Comply with Rule 603.f.		Date: <u>09/17/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Truck Loadout	<= 1 bbl	
Comment:	Stained soil beneath load out valve on AST.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>10/09/2020</u>
In Containment: Yes			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Perimeter post and wire fencing around pump jack and well head.		
Corrective Action:			Date:
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Operating during this inspection.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	HEATED STEEL AST		37.018609,-106.876678
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Secondary containment berm also encompasses AST for Nielson #4.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 296015 Type: WELL API Number: 007-06253 Status: PR Insp. Status: EI

Facility ID: 477321 Type: Domestic Tap API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On September 2, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Albert Martinez #1. For the most recent field inspection report of this facility, please refer to document #688800544.</p> <p>Weeds are present on location and at the tank battery. Remove weeds from facility to comply with Rule 603.f.</p> <p>Stained soil was observed beneath the load out valve on the eastern AST. Control and contain spills/releases and clean up per Rule 906.a.</p>	hughesjo	09/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800799	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5243737