

**Inspection Photos**  
**Location Name: Black Resources State 36-11**  
**API #: 083-06519**



**Weed debris and wellhead from 5/15/20 inspection**



**Corrective action satisfactorily performed**



**Inspection Photos**  
**Location Name: Black Resources State 36-11**  
**Api # : 083-06519**



**H2S sign on fence post of location fence at entrance to location. On-shore Order No. 6 requires signage on access 200' before entrance to location.**



**Inspection Photos**  
**Location Name: Black Resources State 36-11**  
**API #: 083-06519**



**Thistle debris cited in previous inspection**



**Debris removed and new thistle growth**



## Inspection Photos

Location Name: Black Resources State 36-11

Api # : 083-06519



H2S sign on fence post of location fence at entrance to location. On-shore Order No. 6 requires signage on access 200' before entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Black Resources State 36-11**  
**API #: 083-06519**



**Well sign with different contact number (unused equipment?)**



**Trash/debris on side of access road**