

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2020

Submitted Date:

09/08/2020

Document Number:

688800787

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216004	WELL	PR		GW	067-07610	FC ARMSTRONG 001 1	EI
477724	SPILL OR RELEASE	AC	09/04/2020		-	FC ARMSTRONG 001 #1	EI

General Comment:

On August 26, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP America Production Company FC Armstrong 001 #1. For the most recent field inspection report of this facility, please refer to document #687905624. This site visit was in response to Spill/Release Point ID #477724.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Simcoe LLC listed as the operator.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing on pump jack.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical injection system.		
Corrective Action:			Date:

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216004 Type: WELL API Number: 067-07610 Status: PR Insp. Status: EI

Facility ID: 477724 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Please refer to Spill/Release Point ID #477724 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 10/08/2020

Reportable: YES

GPS: Lat 37.114651

Long -107.808541

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical containers.

Comment: "Trapper" containment device on well head.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On August 26, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP America Production Company FC Armstrong 001 #1. For the most recent field inspection report of this facility, please refer to document #687905624. This site visit was in response to Spill/Release Point ID #477724.</p> <p>During this inspection stained soil was observed around the cellar and wellhead. The lube oil and chemical injection system containers are on secondary containment. A "Trapper" containment device is in place around the stuffing box.</p>	hughesjo	09/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402483559	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5241032
688800788	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5241029