

Inspection Photos
Operator: BP America
API: 067-06481
Date: 9/11/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass and rubber rabbitbrush.



Photo 3. View of erosional channel, approximately two feet wide and deep, forming from a shallow headcut in the southwestern corner of the project area.



Photo 4. View of reference area vegetation comprised of open pinyon and juniper woodland, with understory of sagebrush, western wheatgrass, squirreltail, and Indian ricegrass.