

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2020

Submitted Date:

09/17/2020

Document Number:

696103743**FIELD INSPECTION FORM**Loc ID 302582 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299573	WELL	SI	08/01/2018	OW	123-29423	ROUSE USX A 05-08	SI

General Comment:

This is a WELL inspection.

Well(s): 1: Shut-In | SI.

Battery: Inactive | Shut-down.

Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455).
(Well(s): 9: Shut-In | SI).Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629
for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Corrective Action date: 10/02/2020. See photo #1.			
Corrective Action:	Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photo #1.			Date: 10/02/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	Appears plumbed to surface.			

Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.522864,-104.564086
Comment:	Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455). Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 299573 Type: WELL API Number: 123-29423 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Locked-Out, Tagged-Out | LOTO.
COGCC records indicate last production: 07/2018.
SI/TA well per Alternative Mechanical Integrity Assurance Program
(Alternative Program). Doc #02385001 (NOBLE).

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 09/16/2020 at approximately 13:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROUSE USX A-66N64W /5SENE Location ID: 302582 Well Name: Rouse USX A 05-08 API: 05-123-29423 Location County: Weld County, Colorado Weather: Mostly clear w/ haze, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455). (Well(s): 9: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 10/02/2020. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/17/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103744	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250575