

Inspection Photos
Operator: Hilcorp Energy
API: 067-07031
Date: 8/11/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, *Heterotheca villosa*, and snakeweed.



Photos 3/4. View of wattles in the western and southwestern project area that are full of sediment, displaced, and no longer functioning. Wattles are not adequate BMPs in these areas.



Photo 5. View of musk thistles within the western project area that are in flowering condition and dispersing seed. Approximately 25 individuals observed.



Photo 6. View of reference area comprised of ponderosa pine woodland with gambel oak understory, with a mosaic of open grassland largely comprised of smooth brome and western wheatgrass.