



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue, WH has a leak around casing and bradenhead riser.		
Corrective Action:	Comply with Rule 650.d	Date:	09/29/2020
Type	OTHER		
Comment:	Stained soil around WH and braden head riser		
Corrective Action:	Comply with Rule 907.e	Date:	09/29/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 248360 Type: WELL API Number: 123-16158 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/14/2020 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Anderson 22-32 at API #05-123-16158 in Weld County Colorado. While there, I observed a wellsite. During this inspection the following possible compliance issues were observed: 605.d Mechanical Issue: WH is leaking around the tubing &amp; appears to have a leak from the Braden head riser , CA date 9-29-2020 see photos 3 &amp; 4. 907.e Stained soil: stained soil around WH and braden head riser CA date 9-29-2020 see photos 5 &amp; 6. See attached photos. Location is dry, weather is clear. At 1217 hrs I spoke with Manny Silva with KP Kauffman, told him about issues i observed and he said he would get the operator out to take care of the problem. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	09/14/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402488907	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246890</a>
699302544	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246881</a>