

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Inadequate. Displays wrong well name.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 10/14/2020
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: 09/01/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Bradenhead			# 1
Comment:			
Corrective Action:			Date:
Type: Plunger Lift			# 1
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 243599 Type: WELL API Number: 123-11391 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>This is a follow up inspection to previous inspection DOC#: 679602785. One out of two corrective actions have been resolved. The previous corrective action that has not been completed was re-assigned to this location with its original corrective action date. One new corrective action was observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Monday, September 14, 2020 at approximately 12:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at STRONG 1-7 (KP Kauffman), at location #: 319516 in WELD COUNTY Colorado. While there, I observed a producing wellhead. During this inspection the following possible compliance issues were observed: 1. Wellhead sign installed with wrong wellhead name and API #. Install sign to comply with Rule 210.b. (Corrective Action Date: October 14, 2020) See attached photo #1. 2. Stained soil under master valve at wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d. (Corrective Action Date: September 1, 2020) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603301	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5252282